



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D3914-041
Job Sheet 186857



Part No: D3914-041

Job Qty: 1 ea

Part Name: Long Basket Lid Assembly (350)



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 11/22/18

Job Tracking No:

Due Date: 12/7/18

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: DWG D4020 REV A SHEET 2, D3914 REV D SHEETS 1,2,3 IPP Rev:A new issue DD 10.03.19 verified by:EC
IPP Rev:B as per dwg revB DD 10.08.18 verified by:EC IPP Rev:C 13.03.14 AS PER DWG REV.pc1 DD
VERF:JLM IPP REV:D 13.06.21 DWG REV:C DD VERF:JFS

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea	12/7/18	12/7/18	0.00	0.00	Start Up Large Fab-5		<i>C 11/22/2018</i>
100	Large Fab	1 pcs	12/7/18	12/7/18	0.00	6.67	Large Fab 1		<i>C 11/22/2018</i>
110	QC	1 pcs	12/7/18	12/7/18	0.00	0.00	QC9		<i>11/22/2018</i>
120	QC	1 pcs	12/7/18	12/7/18	0.00	0.00	QC5		<i>11/22/2018</i>
130	Powdercoat	1 pcs	12/7/18	12/7/18	0.00	0.40	Powdercoat4		<i>BR 18-12-19</i>
135	QC	1 pcs	12/7/18	12/7/18	0.00	0.00	QC3		<i>BR 18-12-19</i>
140	HandFinish	1 pcs	12/7/18	12/7/18	0.00	0.80	HandFinish3		<i>BR 18-12-19</i>
150	QC	1 pcs	12/7/18	12/7/18	0.00	0.00	QC3		<i>BR 18-12-19</i>
160	Packaging	1 pcs	12/7/18	12/7/18	0.00	0.00	Packaging3-2		<i>BR 18-12-19</i>
170	QC21-SA	1 Ea	12/7/18	12/7/18	0.00	0.00	QC21		<i>21 DEC 20 2018</i>

Part Op 100 - 1- assemble ribs , weld as per dwg D3914 using DT9607A 2- weld hinge (3) and Mounting brackets as per dwg
Descriptions: D3914 ***Visual inspect before welding mesh*** 3- tack weld mesh on basket as per dwg D3914 ***Cut out mesh where
label plate goes in center off basket lid as per dwg D4020-5. Make sure to place mesh correctly on lid, check with label
plate before tacking mesh***

130 - *** mask sides of hinge prior to powdercoat***

140 - Mask data plate and apply wing walk on outside surface of mesh as per dwg 2- Install label as per dwg ***Mask
label plate to size of label, use scotchbrite red pad to lightly sand area for label, apply label***

M 138834 START: 10:25 O.V.T: 320° FINISH: 10:55.

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D2581	Mounting Bracket	2 Ea (2 ea)	90-Start up Operation	<i>5112888</i>
D3914-1	Rib	2 Ea (2 ea)	90-Start up Operation	<i>5123503</i>
D3914-7	Rib	2 Ea (2 ea)	90-Start up Operation	<i>5125626</i>
D4016-3	Hinge Half, Lid	3 Ea (3 ea)	90-Start up Operation	<i>5121277</i>
D4018-5	Rib	9 Ea (9 ea)	90-Start up Operation	<i>5125582</i>
D4020-5	Mesh (350 Basket Long, Lid)	1 Ea (1 ea)	90-Start up Operation	<i>5113439</i>
D4021-3	Data Plate	1 Ea (1 ea)	90-Start up Operation	<i>5114284</i>
D4035-043	Lid Rib Assembly, Aft (350 Basket)	2 Ea (2 ea)	90-Start up Operation	<i>5123320</i>

wing walk. M138963.

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
-----------	----------------	----------	-----------	-----------

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS <table style="width:100%; border: none;"> <tr> <td style="width:15%;">Skid-tube ☐</td> <td style="width:15%;">Cross tube ☐</td> <td style="width:15%;">Water Jet ☐</td> <td style="width:15%;">Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>						Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐																						
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐																						
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐																						
Large Fab ☐	Composite ☐	Supplier ☐																							
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval																		
Description Work Order Deviation				Disposition				Completed By																	
								Lead hand / Supervisor Approval Verification																	
								QC / QA Coordinator Approval																	
Root Cause		FAULT CATEGORY																							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐																				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐																				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐																				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐																				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐																				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐																				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐																				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐																				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐																				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐																				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____																							
Misidentified ☐	Past Due ☐																								

90-Start up Operation

D2581	2	58	0
D3914-1	2	8	0
D3914-7	2	10	0
D4016-3	3	205	0
D4018-5	9	27	0
D4020-5	1	2	0
D4021-3	1	19	0
D4035-043	2	8	0

Part Specifications

Specifications could not be found.

Plex 11/22/18 8:43 AM Dart.lajeunesse.marie

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS <table style="width: 100%; border: none;"> <tr> <td style="border: none;">Skid-tube ☐</td> <td style="border: none;">Cross tube ☐</td> <td style="border: none;">Water Jet ☐</td> <td style="border: none;">Engineering ☐</td> </tr> <tr> <td style="border: none;">Machining ☐</td> <td style="border: none;">Small Fab ☐</td> <td style="border: none;">Prod. Eng. Coord. ☐</td> <td style="border: none;">Quality ☐</td> </tr> <tr> <td style="border: none;">Thermoforming ☐</td> <td style="border: none;">Finishing ☐</td> <td style="border: none;">Rec/Store/Packaging ☐</td> <td style="border: none;">Other ☐</td> </tr> <tr> <td style="border: none;">Large Fab ☐</td> <td style="border: none;">Composite ☐</td> <td style="border: none;">Supplier ☐</td> <td></td> </tr> </table>				Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐				
Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐																					
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐																					
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐																					
Large Fab ☐	Composite ☐	Supplier ☐																						
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval																				
Description Work Order Deviation		Disposition		Completed By																				
DART Aerospace Ltd. 1270 Aberdeen Street Hawkesbury, ON K6A 1K7 CANADA TEL: 1 613 632-5200 Email: sales@dartaero.com www.dartaerospace.com				Lead hand / Supervisor Approval Verification																				
				QC / QA Coordinator Approval																				
Substation ☐ Past Expiry Date ☐ Misidentified ☐		FAULT CATEGORY <table style="width: 100%; border: none;"> <tr> <td style="border: none;">☐ Power Loss/Surge</td> <td style="border: none;">☐ Positioned Wrong</td> </tr> <tr> <td style="border: none;">☐ Folio/Program</td> <td style="border: none;">☐ Outside Dimensions</td> </tr> <tr> <td style="border: none;">☐ Grain</td> <td style="border: none;">☐ Over/Under tolerance</td> </tr> <tr> <td style="border: none;">☐ Weld</td> <td style="border: none;">☐ Part Incorrect</td> </tr> <tr> <td style="border: none;">☐ Wrong Stock Pulled</td> <td style="border: none;">☐ Part Lost/Missing</td> </tr> <tr> <td style="border: none;">☐ Out of Sequence</td> <td style="border: none;">☐ Part Moved</td> </tr> <tr> <td style="border: none;">☐ Off-set</td> <td style="border: none;">☐ Drawing</td> </tr> <tr> <td style="border: none;">☐ Mislabeled</td> <td style="border: none;">☐ Finish</td> </tr> <tr> <td style="border: none;">☐ Fit/Function</td> <td style="border: none;">☐ Misread</td> </tr> <tr> <td style="border: none;">☐ Misaligned/off center</td> <td style="border: none;">☐ Turning Sequence</td> </tr> </table>		☐ Power Loss/Surge	☐ Positioned Wrong	☐ Folio/Program	☐ Outside Dimensions	☐ Grain	☐ Over/Under tolerance	☐ Weld	☐ Part Incorrect	☐ Wrong Stock Pulled	☐ Part Lost/Missing	☐ Out of Sequence	☐ Part Moved	☐ Off-set	☐ Drawing	☐ Mislabeled	☐ Finish	☐ Fit/Function	☐ Misread	☐ Misaligned/off center	☐ Turning Sequence	
☐ Power Loss/Surge	☐ Positioned Wrong																							
☐ Folio/Program	☐ Outside Dimensions																							
☐ Grain	☐ Over/Under tolerance																							
☐ Weld	☐ Part Incorrect																							
☐ Wrong Stock Pulled	☐ Part Lost/Missing																							
☐ Out of Sequence	☐ Part Moved																							
☐ Off-set	☐ Drawing																							
☐ Mislabeled	☐ Finish																							
☐ Fit/Function	☐ Misread																							
☐ Misaligned/off center	☐ Turning Sequence																							
Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		Instructions Incomplete/Unclear ☐ Drill Holes ☐																						
OTHER : _____																								

DART Aerospace Ltd.
 1270 Aberdeen Street
 Hawkesbury, ON K6A 1K7
 CANADA
 TEL: 1 613 632-5200
 Email: sales@dartaero.com
 www.dartaerospace.com



Container No: S136765



Part: D3914 - 041

Job No: 186857

Serial No/Batch: S136765

Revision: A/D

Inspector:

Exp Date:

Instructions: Various STC's

Date: 12/11/18